Barrington Consulting Group,

Copyright

2002

2002\02031\02031.dwg

FORM C:\SCI2\LIBRARY\FORMS\BCGA3-IDWG

1. BENCHMARK - TOP STEM OF EXISTING FIRE HYDRANT LOCATED IN FRONT

4. CONTRACTOR RESPONSIBLE FOR CONTACTING THE OHIO UTILITY PROTECTION SERVICE (1.800,362,2764) AND ALL UTILITY COMPANIES A


UNDERGROUND UTILITIES SHOWN HEREON, HAVE BEEN OBTAINED BY A DILIGENT AND COMPREHENSIVE SEARCH OF AVAILABLE RECORDS. VERIFICATION BY FIELD OBSERVATION HAS BEEN CONDUCTED WHERE PRACTICAL, HOWEVER, BARRINGTON CONSULTING GROUP, INC. DOES NOT

6. CONTRACTOR SHALL VERIFY ELEVATIONS OF LATREAL INVERTS IN THE

DESCRIBED IN THE RAIN WATER LAND DEVELOPMENT MANUAL AS DIRECTED BY THE LAKE COUNTY SOIL AND WATER CONSERVATION

8. TEMPORARY SEEDING SHALL BE APPLIED ON ALL DISTURBED SOIL THAT WILL NOT BE REWORKED FOR WITHIN 30 DAYS. THESE IDLE AREAS TO BE

"I THE UNDERSIGNED HEREBY CERTIFIES THAT THIS TOPOGRAPHY INDICATED BY 1 FOOT CONTOURS AND ELEVATION SHOWN HEREON REPRESENTS AN ACTUAL SURVEY MADE BY ME ON THE 11th DAY OF APRIL. 2002 AND THE ELEVATIONS WERE TAKEN AT AN APPROPRIATE INTERVAL



arrıng CONS 38342 2

DAVID NOVAK 3-7507

CONSTRUCTION, INC NEUBERT

02031